

**List of  
Service Bulletin / Service Letters  
Type EA-300, incl. Models (TCDS N° EASA.A.362)**

N°	Date	Subject	EA-300	EA-300/S	EA-300/L	EA-300/200 EXTRA 200	EA-300/SC	EA-300/LT	EA-300/LC EXTRA 330LX	Airworthiness Directive (AD) / Lufttüchtigkeitsanweisung (LTA)
SB-300-1-91 Issue B	22.10.91	Main Undercarriage U- Spring mounting Clamp	V1, 03, 05, 06, 15 thr. 26	-/-	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-1-92 Issue A	27.03.92	Elevator Mass Balance	V1, 01 thr. 34	-/-	-/-	-/-	-/-	-/-	-/-	LBA: LTA-Nr. 92-199; FAA: AD 98-06-03
SB-300-1-93 Issue B	09.02.93	Rudder Control Cable Compression Sleeve	all	all	-/-	-/-	-/-	-/-	-/-	LBA: LTA-Nr. 93-081; FAA: AD 98-09-10
SB-300-2-93 Issue C	23.08.93	Wing Root Rib/Aux. Spar Attachment	V1, 01 thr. 45	01 thr. 12	-/-	-/-	-/-	-/-	-/-	LBA: LTA-Nr. 93-145/2
SB-300-3-93 Issue B	10.06.98	Upper Longeron Cutout- Bridge	V1, 01 thr. 50	01 thr. 17	-/-	-/-	-/-	-/-	-/-	LBA: LTA-Nr. D-1994-043R1 EASA: 2004-5312 FAA: AD 2005-01-17
SB-300-1-94 Issue A	-	N° withdrawn	-/-	-/-	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-2-94 Issue A	16.06.94	Attachment of engine control bowden Cables	V1, 01 thr. 52	01 thr. 23	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-3-94 Issue A	03.08.94	Canopy Latches	-/-	01 thr. 24	-/-	-/-	-/-	-/-	-/-	LBA: LTA-Nr. 94-258 FAA: AD 98-04-01
SB-300-4-94 Issue A	31.01.95	Pitot Static Drain Installation	V1, 01 thr. 43	01 thr. 12	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-5-94 Issue A	31.01.95	Air Inlet Screen	V1, 01 thr. 51	01 thr. 21	-/-	-/-	-/-	-/-	-/-	LBA: LTA-Nr. 95-125
SB-300-6-94 Issue A	31.01.95	Fire Protection Cowling Area and Firewall	V1, 01 thr. 53	01 thr. 22	-/-	-/-	-/-	-/-	-/-	LBA: LTA-Nr. 95-126
SB-300-7-94 Issue A	31.01.95	Fuel Selector	-/-	01 thr. 24	-/-	-/-	-/-	-/-	-/-	-/-

**List of  
Service Bulletin / Service Letters  
Type EA-300, incl. Models (TCDS N° EASA.A.362)**

N°	Date	Subject	EA-300	EA-300/S	EA-300/L	EA-300/200 EXTRA 200	EA-300/SC	EA-300/LT	EA-300/LC EXTRA 330LX	Airworthiness Directive (AD) / Lufttüchtigkeitsanweisung (LTA)
SB-300-8-94 Issue A	31.01.95	Hydraulic Brakes	V1, 01 thr. 54	01 thr. 25	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-1-95 Issue A	09.01.95	Seat Attachment	V1, 01 thr. 63	01 thr. 22	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-2-95 Issue F	10.07.06	Upper Longeron Insp.	01 thr. 62	01 thr. 29	01 thr. 71 73 thr. 77 79 thr. 83 85 thr. 89 91 and 92	01 thr. 31 1032 thr. 1039	-/-	-/-	-/-	EASA: AD N° 2006-0281 FAA: AD 2007-02-11 LBA: D-2003-001R1
SB-300-3-95 Issue B	12.05.98	Rudder pedal safety control stop	all, if electric actuated pedals installed, prior 11/1995	01 thr. 028	01 thr. 15	-/-	-/-	-/-	-/-	LBA: LTA-Nr. 95-443; FAA: AD 98-CE-53-AD
SB-300-1-96 Issue A	-	N° withdrawn	-/-	-/-	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-1-97 Issue B	11.06.97	Front Seat Belt Safety Cover Installation	-/-	-/-	-/-	01 thr. 15	-/-	-/-	-/-	LBA: LTA-Nr. 97-203 R2 FAA: AD 97-22-03
SB-300-2-97 Issue D	12.12.16	Fuselage Structure Tail Spring Support	-/-	-/-	012, 014 thr. 170, 172, 173, 1171 and 1174 thr. 1299	01 thr. 31 and 1032 thr. 1043	-/-	-/-	-/-	EASA: AD N° 2009-160 LBA: LTA-Nr. D-1998-001R1 FAA: AD 2010-04-11 Transport Canada: Validated
SB-300-1-98 Issue A	19.03.98	Front seat installation of lap belt guide	-/-	-/-	-/-	01 thr. 23	-/-	-/-	-/-	LBA: LTA-Nr. 97-203 R2; FAA: AD 97-22-03
SB-300-1-01 Issue A	26.03.01	Securing the wire stirrup of the gascolator bowl	1 thr. 67	1 thr. 30	1 thr. 133	1 thr. 29	-/-	-/-	-/-	-/-

N°	Date	Subject	EA-300	EA-300/S	EA-300/L	EA-300/200 EXTRA 200	EA-300/SC	EA-300/LT	EA-300/LC EXTRA 330LX	Airworthiness Directive (AD) / Lufttüchtigkeitsanweisung (LTA)
SL-300-09-02 Issue A	19.09.02	Fuel selector valve leakage	-/-	all	all	all	-/-	-/-	-/-	LBA: LTA-Nr. 2002-408 FAA: AD 2003-17-02
SB-300-1-04 Issue A	25.03.04	Replacement Fuel Hose to Filler Cap	-/-	01 thr. 31	01 thr. 167, 168 (or 1168) 169 (or 1169) 170 (or 1170) 172 and 173 (or 1173)	01 thr. 31	-/-	-/-	-/-	-/-
SL-300-1-04 Issue A	Sep. 04	Technical Publications	-/-	-/-	-/-	-/-	-/-	-/-	-/-	-/-
SB-300-2-04 Issue C	24.11.05	Inspection/repair of Main Landing Gear Mounting Attachment	-/-	-/-	-/-	01 thr. 31 and 1032 thr. 1034	-/-	-/-	-/-	-/-
SB-300-3-04 Issue A	30.04.04	Change Long Range Tanks- to Standard Tanks Configuration	64 thr. 67	29 thr. 31	06 thr. 167, 168 (or 1168) 169 (or 1169) 170 (or 1170) 172 and 173 (or 1173)	-/-	-/-	-/-	-/-	-/-
SB-300-4-04 Issue A	25.05.04	Bottom fuselage cover/firewall sealing	V1, 01 thr. 67	01 thr. 31	01 thr. 167, 168 (or 1168) 169 (or 1169) 170 (or 1170) 1171, 172, 173 (or 1173) and 1174 thr. 1181	01 thr. 31	-/-	-/-	-/-	LBA: LTA-Nr. D-2004-489; FAA: AD 2005-11-07

N°	Date	Subject	EA-300	EA-300/S	EA-300/L	EA-300/200 EXTRA 200	EA-300/SC	EA-300/LT EXTRA 300LT	EA-300/LC EXTRA 330LX	Airworthiness Directive (AD) / Lufttüchtigkeitsanweisung (LTA)
SB-300-1-05 Issue A	27.07.05	Engine fuel pump vent	V1, 01 thr. 67	01 thr. 31, 1032	01 thr. 167, 168 (or 1168) 169 (or 1169) 170 (or 1170) 1171, 172 (or 1172), 173 (or 1173) , 1174 thr. 1199 and 1201 thr. 1203	-/-	-/-	-/-	-/-	-/-
SB-300-1-06 Issue A	18.08.06	Repositioning of Single Oil Cooler	-/-	aircrafts equipped with the single oil cooler system manufactured before May 2006	aircrafts equipped with the single oil cooler system manufactured before May 2006	-/-	-/-	-/-	-/-	-/-
SB-300-1-11 Issue A	18.07.11	Safety clamps on Garmin avionics units located in subpanels	aircrafts manufactured before July 2011 and equipped with Garmin avionics units	aircrafts manufactured before July 2011 and equipped with Garmin avionics units	aircrafts manufactured before July 2011 and equipped with Garmin avionics units	aircrafts manufactured before July 2011 and equipped with Garmin avionics units	aircrafts manufactured before July 2011 and equipped with Garmin avionics units	aircrafts manufactured before July 2011 and equipped with Garmin avionics units	aircrafts manufactured before July 2011 and equipped with Garmin avionics units	-/-
SL-300-1-14 Issue C	30.06.22	Propeller blade lag screw replacement (addresses MT-Propeller SB N°30 [R7])	all	all	all	all	all	all	all	-/-

N°	Date	Subject	EA-300	EA-300/S	EA-300/L	EA-300/200 EXTRA 200	EA-300/SC	EA-300/LT EXTRA 300LT	EA-300/LC EXTRA 330LX	Airworthiness Directive (AD) / Lufttüchtigkeitsanweisung (LTA)
SB-300-1-15 Issue A	29.05.15	Throttle control cables	-/-	01 thr. 31, 1032, 1034, 1036	01 thr. 167, 168 (or 1168) 169 (or 1169) 170 (or 1170) 1171, 172 (or 1172), 173 (or 1173), 1174 thr. 1326	01 thr. 31, 1032 thr. 1046	SC003 thr. SC054	LT001 thr. LT030	LC001 thr. LC043	
SB-300-1-16 Issue A	14.01.16	V-tubes in rear fuselage structure	62	-/-	-/-	-/-	-/-	-/-	-/-	-/-
SL-300-1-21 Issue A	07.05.21	Replacement of discontinued Bosch Alternator with Prestolite Alternator	-/-	-/-	All, when equipped with Bosch Alternator	-/-	-/-	-/-	-/-	-/-
SL-300-2-21 Issue A	19.10.21	Replacement of discontinued GARMIN GTN Series with GTN Xi	-/-	-/-	-/-	-/-	-/-	All, when equipped with Garmin GTN Series	All, when equipped with Garmin GTN Series	-/-
SB-300-1-22	11.02.22	Non-destructive inspection (NDI) fuselage structure	-/-	-/-	-/-	-/-	All	-/-	-/-	
SB-300-2-22	12.07.22	Recurrent inspection of elevator trim tab	All	All	All	-/-	-/-	All	All	