

## SERVICE BULLETIN No. 300-8-94

### Information Only

Subject: Hydraulic Brakes

Models affected: EA-300 EA-300/S

Serial numbers affected: V1, 01 through 54 01 through 25

Purpose: Brake performance on aircraft frequently operated at or close to normal category MTOW can be improved by changing to a higher rated brake system.

Approval: The technical content of this Service Bulletin have been approved by LBA.

---

#### Instructions:

- Change the existing brakes (Cleveland Type 30-9) and wheels (Cleveland Type 40-78B) to the stronger Cleveland brakes type 30-164 and corresponding Cleveland wheels 40-151.
- Details for the work involved including ground run conditioning are found in the EXTRA Service Manual Chapter 32-40.
- Make appropriate entry of compliance with this service bulletin in the aircraft logbook.

#### Note:

- Alterations or repair of the aircraft must be accomplished by licenced personell only.