

## SERVICE BULLETIN No. 300-5-94

### Compliance mandatory

Subject: Air Inlet Screen  
Models affected: EA-300 EA-300/S  
Serial numbers affected: V1,01 through.51 01 through 21  
Purpose: Improvement of Engine Air Inlet  
Approval: The technical content of this Service Bulletin have been approved by LBA.

---

Compliance time: At next 100h inspection or annual inspection whichever comes first.

Information:

- The provision of the air inlet screen will reduce the exposure of the engine to any particles entering the injector throat. Especially in case of a bird strike the screen will ensure that not both air intakes, normal and alternate through cowling bypass, are effectively blocked simultaneously.

Instructions:

- For information of required material and the installation please refer to Modification Instruction UA-300-3-94

Note:

- Alterations or repair of the aircraft must be accomplished by licensed personell only.